


NOTES:

1. IF INSTALLATION IS MADE BY THE PROPERTY OWNER, WATER WILL NOT BE TURNED ON UNLESS THE DISTRICT HAS RECEIVED A SATISFACTORY CERTIFIED TEST REPORT AND THE INSTALLATION MEETS ALL OTHER DISTRICT REQUIREMENTS.
2. IT IS THE CONSUMERS RESPONSIBILITY TO HAVE THE DOUBLE CHECK VALVE ASSEMBLY CHECKED ON A YEARLY BASIS AND TO KEEP IT IN GOOD OPERATING CONDITION.
3. 3" INSTALLATIONS AND ABOVE SHALL BE WESTERN CHAIN LINK ENCLOSURE.
4. 3" INSTALLATION AND ABOVE SHALL BE DUCTILE IRON PIPE.



NO.	REV. DATE	BY
1	OCT. 1992	JO
2	APR. 1994	JO
3	JAN. 1998	BEC
4	DEC. 2003	BEC
5	DEC. 2014	KSB

DOUBLE CHECK VALVE ABOVE GRADE

APPROVED BY

Daniel McBrath

MANAGER

01/2015
DATE

STANDARD
PLAN

6A